

General Environmental Incident Summary

Incident: 3732 **Date/Time Notice:** 4/23/2015 2229 **DEM Incident No:**

Responsible Party: JMAC Resources, Inc.

Date Incident: 4/23/2015 **Time Incident:** 2000 **Duration:** 2 hours

County: Williams **Twp:** 154 **Rng:** 100 **Sec:** 15 **Qtr:**

Lat: 48.15455 **Long:** -103.53140 **Method:** Interpolation from map

Location Description: from Williston go East on 1804. incident site is 3.25 miles east of the Little Muddy River Bridge on the North side of the highway.

Submitted By: Chris Kreger

Affiliation: Environmental Specialist

Address: 121 48th Ave. SW

City: Williston

State: ND

Zip: 58801

Received By:

Contact Person: Russel Mudder
121 48th Ave. SW
Williston, ND 58801

Distance Nearest Occupied Building: 750 Feet

Release Contained: Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: 5 gallons of deisel full and 25 tons of solidified drill cuttings

Volume Spilled: 5.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Vehicle drove off shoulder of pavement. The driver reacted to pull the truck back on the road and caused the truck to roll over.

Risk Evaluation:

none

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Drill cuttings and contaminated soils will be removed within 10 to 12 hours. Significant migration is highly unlikely.

Action Taken or Planned:

Site is secured and contaminated materials will be removed during daylight hours. No threat to waters of the State is apparent or imminent.

Wastes Disposal Location: IHD Solids Management.

Agencies Involved: State Highway Patrol

Updates

Date: 4/23/2015 **Status:** Reviewed - Assigned to NDDoH Division

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill involved a minimal amount of liquid released and a large amount of oilfield waste. Forward to Division of Waste Management.

Date: 5/18/2015 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Volume:

Notes:

Received an email with attached report documenting the spill and cleanup. Cleanup was conducted properly and showed minor (12.5 ppm) petroleum impacts to the remaining soils at the location. Report and email in database. No further action at this time.